


N330EX



mt-propeller

The Winner's Propeller

PROPELLER LOGBOOK

EASA DE.21G.0008 / EASA.21J.020

MTE - 1198
Juni 2005

Owner Name _____

Address _____

Propeller Model MTV-9-B-C

Blade Model C198-25

Hub Serial No. 160598

Blade Serial No. 1 AHC - 60577

2 AHC - 60578

3 AHC - 60579

4 

5 _____

6 _____

Propeller Diameter: 198 cm ± 0.5 cm

Low Pitch: 9.5 ° ± 0.2 ° TCI: 72 Month


High Pitch: 34 ° ± 1 ° TBO: 2400 Hrs.

Feathering: / ° ± / °


Reverse: / ° ± / °

at radius station: 74 cm

INSTALLATION HISTORY

Date	Aircraft Model, Registration & Serial No., Tacho or Hobbs-Time
21.09.2016	Installed on EA200/LT SN LT039 @ Glen Tairā EXTRA DE.21G.0180 EXTRA QM-015 

MAINTENANCE & SERVICE HISTORY

Date	Total Propeller Time	Time Since Overhaul	Description Of Work	Authorized Signatures Repairman and Station Certificate Numbers
July 27 2016	00:00	—	Manufactured	

SOUTHEAST AERO SERVICES, INC. 800-692-2091
EXTRA FLUGZEUGPRODUKTIONS EA-300/LT S/N LT039 N330EX

November 11, 2016 Time .5

Mtv-9-B-C/C198-25 S/N: 160598

- 1.) Completed a 100hr. Insp. In Accordance With Mt-Propeller Service Manual E-124
- 2.) Complied with Ad Summary thru Revision 2016-23 as follows.
- 3.) A.D. 2007-26-13 MT-Propeller Entwicklung GmbH: Amendment 39-15315. To prevent erosion sheath separation leading to damage of the airplane. **Is not applicable by Serial Number.**
- 4.) Installed spinner and blade cut-outs.

I certify that this propeller has been inspected in accordance with the scope and detail of Appendix D to Part 43, and found to be in a condition for safe operation.

Douglas I Vayda A&P26940361A


MAINTENANCE & SERVICE HISTORY

Date	Total Propeller Time	Time Since Overhaul	Description Of Work	Authorized Signatures Repairman and Station Certificate Numbers
------	----------------------	---------------------	---------------------	---

SOUTHEAST AERO SERVICES, INC. 800-692-2091
EXTRA FLUGZEUGPRODUKTIONS EA-300/LT S/N LT039 N330EX

September 2, 2017

Mtv-9-B-C/C198-25 S/N: 160598

- 1.) Completed A Condition/Annual Insp In Accordance With Mt-Propeller Service Manual E-124
- 2.) Complied with Ad Summary thru Revision 2017-17 as follows.
- 3.) A.D. 2007-26-13 MT-Propeller Entwicklung GmbH: Amendment 39-15315. To prevent erosion sheath separation leading to damage of the airplane. Is not applicable by Serial Number.
- 4.) Installed spinner and blade cut-outs.

I certify that this propeller has been inspected in accordance with the scope and detail of Appendix D to Part 43, and found to be in a condition for safe operation.

Douglas I Vayda A&P2694036IA

NOTE: Enter Compliance With All Applicable FAA A.D. & Factory Service Bulletins On Pages 11 & 12

MT-Propeller Entwicklung GmbH
Flugplatzstraße 1
D-94348 Atting, Germany
Tel.: +49-(0)9429-9409-0
Fax:+49-(0)9429-8432
E-mail: sales@mt-propeller.com
Internet: www.mt-propeller.com

MT-Propeller USA, Inc.
1180 Airport Terminal Drive
DeLand, FL 32724
USA
Tel.: (386) 736-7762
Fax: (386) 736-7696
E-mail: info@mt-propellerusa.com
Internet: www.mt-propellerusa.com