



mt-propeller

The Winner's Propeller

PROPELLER LOGBOOK

EASA DE.21G.0008 / EASA.21J.020

MTE - 1198
Juni 2005

Owner Name: _____

Address: _____

Propeller Model: _____ MT 233 R 150 - 6AJ _____

Hub Serial No.: _____ 15018 _____ Year of Construction: 2015

Please note that the torque of prop mounting bolts must be rechecked after first flight, next after 25 hours and than latest every 100 hours or once a year !

Please check required torque on the decal located at prop hub. In case you can't identify the torque you must contact the next authorized service station. For more information please read the Operating & Installation Manual E-112 sent with propeller.

INSTALLATION HISTORY

Date	Aircraft Model, Registration & Serial No., Tacho or Hobbs-Time
19-11-16	Waco YMP-5C SN106 TACH 150 SEE AF LOG ENTRY DATED 5-11-16

