DATE	TOTAL TIME IN SERVICE	TOTAL TIME SINCE OVERHAUL	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
				AVIATION, LP.
ompleted 6-74/80. I eaned fue o applicate ound run	100 hr. inspectinstalled new cool screen and role AD notes at the checked good	tion of engine. hampion RHB nozzles. Repla this time, see	32E spark plugs ced inlet air filter AD note summa	s checked. Compression check: #1-72/80, #2-73/80, #3-74/80, #4-72/80, #5-72/80, s. Megged ignition harness, checked good. Retimed both mags to 22 degrees BTC Changed oil and cleaned screen, checked good. Serviced with Phillips 20W50 XC. ary in aircraft papers for complete listing and compliance times. Engine washed and
atella	9,2013	sig athu	eted in accordance MOH 232,	ce with a 100 hr. Inspection and determined to be in Airworthy condition. Tach Time 3402.7 Cert# APAI40786
ocket Avi	ation, Plainvie	w, TX		
		8	2	
			3	
· ·				a a
			7	
		ж.	2 2	5
			, v	
			_ 1	
Y LEE				SUB-TOTALS this page



Date: 5/09/2013; Aircraft: N28111; Type: BELLANCA; S/N: 79-30909 Completed 100 hr. inspection of propeller. Removed propeller for blade reseal by Porterfield Propeller. Reinstalled propeller after blade reseal using new seal and torqued. See 8130-3 attached. Inspected hub and blades, checked good. Dressed blades as needed. No applicable AD notes at this time, see AD note summary in aircraft papers for complete listing and compliance times.

I certify that this Propeller has been inspected in accordance with a 100 hr. Inspection and determined to be in Airworthy condition.

Tach Time 3402.7 Prop Total Time 3402.7 Prop Time SMOH 432.7

Date Man 9 2013 Sig Stathung Mitchellicert. # 140786

Rocket Aviation, Plainview, TX

ndria 04 by

19	TIME	FLIGHT	TIME IN SERVICE	Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
		1		TO TO N, L P.
complete shimmy of serviced. extension installation 75-20-06 and grout checked listing an I certify the condition of Tach Tires and the service of the servi	ed Annual Inspectampner and se Resealed left not checked good on of ELT in according check of good. C/W AL add compliance to this Aircraft not.	ection of aircerviced. Adj main gear a d. Serviced cordance wi of truss tubi mag switch 0 87-11-01 l imes. has been i	traft. Serviced usted nose ge ctuating cylind hydraulic pow th FAR 91.20 ng in accordal, checked good by inspection of the properties of t	NCA; S/N: 79-30909 If and lubricated all systems. All routine items checked per Bellanca check list. Resealed and solvent installed new pilot vent window seal. Resealed left main gear strut and der, reinstalled and adjusted per service manual. Checked gear operation and emergency ver pack. Replaced missing wing root fairing screws as needed. Checked operation and 7 (d), checked good. Reinstalled and armed ELT. Battery date: April 2014. C/W AD 7 (d), checked good. Reinstalled and armed ELT. Battery date: April 2014. C/W AD note with Alexandria Aircraft SL #85B, checked good. C/W AD 76-07-12 by inspection and C/W AD 76-08-04 by inspection of wood in accordance with Bellanca SL #87A, of fuel caps and scupper drains, checked good. See AD note summary for complete accordance with an ANNUAL Inspection and is determined to be in AIRWORTHY The provided Heritage of the provided Heritage SL #32.5 ELT Bat, Date 440004
			. A	
© 1992 ASA				

DATE

19___