#### **AIRFRAME**

Company

Manufacturer

CESSNA AIRCRAFT CORP.

Model Serial # A185F

04147

**Tach Time** 

1101.3

A/C Cert. Date

**Total Time** 

2674.3

Tail Number N61323

AD# Effective	Subject	Date & Hours @ Compliance	Method Of Compliance	0	R	Next Comp @ Hrs/Date	Authorized Signature & Number
* <b>68-17-04</b> 09/07/68	STALL WARNING SYSTEM/		N/A BY S/N		X	N/A	3MIR878B
<b>73-23-07</b> 11/19/73	DEFECTIVE SPAR ATTACHMENT FITTINGS/		N/A BY S/N	Х		N/A	3MIR878B
<b>75-09-06</b> 05/05/75	ENGINE INDUCTION AIR DUCT/		N/A BY S/N	X		N/A	3MIR878B
<b>75-16-01</b> 07/30/75	WING FUEL TANK QUANTITY PLACARDS/		N/A BY S/N	Х		N/A	3MIR878B
* <b>76-04-03</b> 02/26/76	ARC PA-500A ACTUATORS/	·	N/A BY S/N		Х	N/A	3MIR878B
<b>77-04-05</b> 03/01/77	CARBURETOR AIR BOX SEAL/		N/A BY STC'd FUEL INJECTED ENGINE INSTALLED	Х		N/A	3MIR878B
<b>77-12-08</b> 06/27/77	EXTERNAL ELECTRIC GROUND POWER RECEP /		N/A BY S/N	Х		N/A	3MIR878B
<b>79-08-03</b> 06/06/79	CIGAR LIGHTER WIRING MODIFICATION/		N/A BY S/N	Х		N/A	3MIR878B
<b>79-10-14 R1</b> 05/30/88	FUEL TANK VENTED CAPS/		N/A BY S/N	Х		N/A	3MIR878B
<b>79-25-07</b> 12/13/79	ALTERNATOR GROUND STRAP/		N/A BY S/N	Х		N/A	3MIR878B
<b>83-17-06</b> 09/01/83	AILERON BALANCE WEIGHTS/	9	N/A STC NOT INSTALLED	Х		N/A	3MIR878B
<b>83-22-06</b> 11/08/83	AILERON HINGE PIN/	6-11-84 482.5	P/C/W PER FIGURE 1 DETAIL A-A DRILLING HOLE AND INSTALLING OVERSIZED PIN	X		N/A	3MIR878B
* <b>84-10-01 R1</b> 07/05/88	BLADDER FUEL CELLS AND QUICK DRAINS/	6-18-93 1459.8	P/C/W MONARCH CAP INSTALLED NO LONGER APPLICABLE		Х	N/A	3MIR878B
* <b>86-19-11</b> 10/04/86	AFM - FUEL TANK AND RESERVOIR QUICK DRAINS/	2-16-12 2674.3	P/C/W BY APPENDIX INSTALLATION INTO AIRCRAFT RECORDS 1/9/89 1160.0 / INSPECTED FUEL DRAINS 12/29/06		Х	EACH PREFLIGHT	3MIR878B
<b>86-24-07</b> 01/07/87	ENGINE CONTROL ATTACHMENT MODIFICATION/		N/A BY S/N	X		N/A	3MIR878B

<sup>\*</sup> indicates possible recurring inspections © 1995 – 2007 - Tdata, Inc. (Tdata.com)

Prepared by / land land | Date 2/16/12

# **Airworthiness Directive Compliance Record**

N61323

Page 2 of 6

* <b>87-20-03 R2</b> 09/24/90	SEAT TRACKS AND SEAT PIN ENGAGEMENT/		SUPERCEDED		X	N/A	HLWR727E
<b>87-20-04</b> 09/30/87	FUEL SYSTEM/		N/A BY S/N	Х		N/A	3MIR878B
<b>93-24-15</b> 02/11/94	INSTRUMENT PANEL LIGHT DIMMING RHEOSTAT/		N/A BY S/N	Х		N/A	3MIR878B
<b>97-01-13</b> 02/03/97	S51-10 TYPE OIL, FUEL AND HYDRAULIC HOSES/	4-28-03 408.3 TACH	P/C/W BY INSPECTION OF HOSES FOUND NOT INSTALLED	X		N/A	3MIR878B
<b>98-16-04</b> 09/21/98	WING LOWER CAP ANGLE STIFFENER/	×	N/A NOT INSTALLED	X		N/A	3MIR878B
<b>98-23-02</b> 12/22/98	WHEEL SKIS/		N/A NO SKIS INSTALLED AT THIS TIME	X		N/A	3MIR878B
<b>00-06-01</b> 05/05/00	FUEL STRAINER ASSEMBLY STANDPIPE/	7-25-00 404.4	P/C/W BY MEASUREMENT OF STANDPIPEFOUND OK FOR SERVICE	X		N/A	3MIR878B
* <b>01-08-08</b> 06/07/01	V-BAND EXHAUST CLAMP/		N/A NOT TURBO CHARGED	Ì	Х	N/A	3MIR878B
<b>08-10-02</b> 05/12/08	ALTERNATE STATIC AIR SOURCE SELECTOR VALVE/	1-19-09 2561.7	INSPECTION AND REMOVAL OF PLACARD	X		N/A	3MIR878B
<b>08-26-10</b> 01/05/09	PLACARD, ALTERNATE STATIC AIR SOURCE SELECTOR VALVE ID PLACARD/	1-19-09 2561.7	INSPECTION AND REMOVAL OF PLACARD	Х		N/A	3MIR878B
* <b>11-10-09</b> 06/17/11	SEAT TRACK WEAR AND SEAT PIN ENGAGEMENT/	2-16-12 2674.3	INSPECTION OF SEATS AND SEAT TRACKS		Х	N/A	3MIR878B

Prepared by Sulla U

## **ENGINE** -

Company

Manufacturer Model TELEDYNE CONTINENTAL MOTORS

IO-550-D2R

Location Serial #

**TSMOH** 

284048-R

Total Time 1

1101.3

AD# Effective	Subject	Date & Hours @ Compliance	Method Of Compliance	0	R	Next Comp @ Hrs/Date	Authorized Signature & Number
* <b>86-13-04 R3</b> 02/24/88	CYLINDER BARREL CRACKING/		AD's THRU 6-3-94 P/C/W BY FACTORY AT REBUILD		X	N/A	3MIR878B
<b>87-14-02</b> 10/05/87	STARTER ADAPTER SHAFTS/		AD's THRU 6-3-94 P/C/W BY FACTORY AT REBUILD	X		N/A	3MIR878B
<b>88-03-06</b> 04/15/88	TCM PRO-TECH ENGINE OIL FILTER/		AD's THRU 6-3-94 P/C/W BY FACTORY AT REBUILD	X		N/A	3MIR878B
<b>88-17-03</b> 08/10/88	STARTER ADAPTER DRIVE SHAFT/		AD's THRU 6-3-94 P/C/W BY FACTORY AT REBUILD	X		N/A	3MIR878B
<b>91-19-03</b> 09/29/91	CHAMPION ENGINE OIL FILTER/		AD's THRU 6-3-94 P/C/W BY FACTORY AT REBUILD	X		N/A	3MIR878B
<b>93-08-17</b> 08/23/93	OIL PICK-UP TUBE INSPECTION/		AD's THRU 6-3-94 P/C/W BY FACTORY AT REBUILD	X		N/A	3MIR878B
<b>93-10-02</b> 08/12/93	CYLINDER VALVE RETAINER KEY/		AD's THRU 6-3-94 P/C/W BY FACTORY AT REBUILD	X		N/A	3MIR878B
<b>93-16-15</b> 12/14/93	FUEL PUMP DRIVE SHAFT COUPLING/		AD's THRU 6-3-94 P/C/W BY FACTORY AT REBUILD	X		N/A	3MIR878B
* <b>94-09-07</b> 07/05/94	SUPERSEDED BY AD 95-03-14/		SUPERCEDED		X	N/A	
<b>94-14-12</b> 06/23/94	SUPERSEDED BY AD 95-21-15/		SUPERCEDED	X		N/A	
* <b>95-03-14</b> 03/13/95	INSPECTION OF ENGINE MOUNT BRACKETS/		N/A BY MODEL NUMBER		X	N/A	3MIR878B
<b>95-21-15</b> 11/28/95	ENGINE TEARDOWN AND INSPECTION/		N/A BY "N" NUMBER	X		N/A	3MIR878B
* <b>96-12-22</b> 07/31/96	OIL FILTER ADAPTER ASSEMBLY NUT/	12-22-10 2635.3	INSPECTION OF OIL FILTER ADAPTORTORQUE SEAL NOT DISTURBED		Х	OIL FILTER REMOVAL	3MIR878B
<b>98-01-08</b> 12/23/97	EXHAUST ROLLER BEARING ROCKER ARMS/		N/A ROLLER ROCKERS NOT INSTALLED	X		N/A	3MIR878B
<b>99-09-17</b> 04/22/99	SUPERSEDED BY AD 99-19-01/		SUPERCEDED	Х		N/A	

<sup>\*</sup> indicates possible recurring inspections © 1995 – 2007 - Tdata, Inc. (Tdata.com)

Prepared by ///

Date  $\frac{2/16/12}{}$ 

### **Airworthiness Directive Compliance Record**

N61323

Page 4 of 6

<b>99-19-01</b> 09/30/99	CRANKSHAFT CHEEK CRACKS/	N/A BY S/N	X		N/A	3MIR878B
<b>00-08-51</b> 04/28/00	SUPERSEDED BY AD 2000-23-21/	SUPERCEDED	X		N/A	
<b>00-23-21</b> 12/12/00	CRANKSHAFT CONNECTING ROD JOURNAL/	N/A BY S/N	X		N/A	3MIR878B
<b>04-08-10</b> 05/05/04	ENGINE COMPONENTS, INC. STC'D CYLINDERS/	N/A NO ECI CYLINDERS INSTALLED	X		N/A	3MIR878B
<b>07-04-19</b> 03/12/07	REVISED BY AD 2007-04-19 R1/	SUPERCEDED	Х		N/A	
<b>07-04-19 R1</b> 05/07/07	SUPERIOR AIR PARTS, INC. CAST CYLINDER ASSEMBLIES/	N/A NO SUPERIOR AIR PARTS CYLINDERS INSTALLED	Х		N/A	3MIR878B
<b>07-16-10</b> 08/23/07	TURBOCHARGER COMPRESSOR ROTOR/	N/A NOT TURBO CHARGED	X		N/A	3MIR878B
* <b>09-16-03</b> 09/09/09	SUPERIOR AIR PARTS INVESTMENT CAST CYLINDER ASSEMBLIES/	N/A NO SUPERIOR AIR PARTS CYLINDERS INSTALLED		Х	N/A	3MIR878B
* <b>09-19-07</b> 10/07/09	EQ3 CYLINDER HEAD ASSEMBLIES/	N/A NO AFFECTED CYLINDERS INSTALLED		X	N/A	3MIR878B
<b>09-24-51</b> 11/16/09	SUPERSEDED BY AD 2009-24-52/	SUPERCEDED	X		N/A	, V
<b>09-24-52</b> 11/18/09	HYDRAULIC VALVE LIFTERS/	N/A BY MANUFACTURE DATE	X		N/A	3MIR878B
<b>10-11-04</b> 06/16/10	HYDRAULIC VALVE LIFTERS/	N/A BY MANUFACTURE DATE	Х		N/A	3MIR878B
<b>11-25-51</b> 11/29/11	STARTER ADAPTER SHAFT GEAR/	N/A BY MODEL NUMBER	Х		N/A	3MIR878B

Prepared by / En Ch Cf

#### PROPELLER -

Company

Manufacturer

HARTZELL

Model

PHC-C3Y SERIES

Location

N61323

Blade

TSMOH

368.5

Tail # Serial #

EE1835

**Total Time** 

1101.3

Tail Number N61323

AD# Effective	Subject	Date & Hours @ Compliance	Method Of Compliance	0	R	Next Comp @ Hrs/Date	Authorized Signature & Number
<b>77-12-06</b> 12/21/77	77-12-06 R2 IS SUPERSEDED BY AD 2002-09-08/		SUPERCEDED	X		N/A	
* <b>94-17-13</b> 09/15/94	EDDY CURRENT INSPECTION/		N/A BY S/N		X	N/A	3MIR878B
<b>01-07-03</b> 06/04/01	PROPELLERS RETURNED TO SERVICE BY BASCO/		N/A NO WORK BY BASCO	Х		N/A	3MIR878B
<b>02-09-08</b> 06/13/02	SUPERSEDED BY AD 2007-26-09/		SUPERCEDED	Х		N/A	1. 8
<b>03-13-17</b> 07/18/03	MAINTENANCE REPAIR BY T AND W PROPELLERS, INC./		N/A NO WORK BY T & W PROPS	Х		N/A	3MIR878B
<b>05-14-11</b> 08/17/05	MAINTENANCE AND REPAIR BY SOUTHERN CALIFORNIA PROPELLER SERVICE/		N/A NO WORK BY SOUTHERN CALIFORNIA PROPS	X		N/A	3MIR878B
<b>06-24-07</b> 01/03/07	INSPECTIONS AND REPAIRS BY CSE AVIATION/		N/A NO WORK BY CSE AVIATION	X		N/A	3MIR878B
<b>07-26-09</b> 01/30/08	PLACARD, PROPELLER BLADE SHANK REWORK/		N/A BY PROP BLADES S/N'S	Х		N/A	3MIR876B
* <b>08-13-28</b> 07/17/08	PROPELLER HUB LUBRICATION HOLES/		N/A NOT LEFT HANDED PROP		Х	N/A	3MIR878B

Prepared by / Low ()

Date 2/16/12

# **APPLIANCES**

Company

Tail#

N61323

AD# Effective	Subject	Date & Hours @ Compliance	Method Of Compliance	0	R	Next Comp @ Hrs/Date	Authorized Signature & Number
* <b>05-12-06</b> 07/19/05	RIVETED OR SNAP-RING IMPULSE COUPLINGS WITH MODEL CHANGES/		N/A BY ENGINE MANUFACTURE AND MODEL		Х	N/A	3MIR878B) lh l/